

DILL TPMS APPLICATIONS CHART ©

Make	Model	Model Year Range	OE Torque In-Lbs	Dill Kit	Costco Kit	Valve Stem Replacement	Costco Valve	Dill/Costco	Costco
Acura	CSX	08-11	35	2045K	863921	NO	NO	7002 or 7002A	707597 or 1022490
Acura	ILX	13-15	71	7000K	502973	VS70	707594	7002 or 7002A	707597 or 1022490
Acura	ILX	16	71	7000K	502973	VS70	707594	5514	1006938
Acura	MDX	04-06	40	2000K	300415	1096	300415	7002A or 1057	1022490 (RS) or 503013
Acura	MDX	07-13	35	1100K	502921	NO	NO	7002A or 1209	1022490 (RS) or 574590
Acura	MDX	14-15	71	7000K	502973	VS70	707594	5512	860476
Acura	MDX	16	71	7000K	502973	VS70	707594	5514	1006938
Acura	RDX	07-12	35	1100K	502921	NO	NO	7002A or 1209	1022490 (RS) or 574590
Acura	RDX	13-15	71	7000K	502973	VS70	707594	5512	860476
Acura	RDX	16	71	7000K	502973	VS70	707594	5514	1006938
Acura	RL	05-08	40	2000K	300415	1096	300415	7002A or 1057	1022490 (RS) or 503013
Acura	RL	09-12	35 or 40	2045K	863921	NO	NO	7002A or 1057	1022490 (RS) or 503013
Acura	RLX	14-15	35	2045K	863921	NO	NO	7002A or 1214	1022490 (RS) or 574251
Acura	TL	06-08	40	2000K	300415	1096	300415	7002A or 1057	1022490 (RS) or 503013
Acura	TL	09-14	35	2045K	863921	NO	NO	7002A or 1214	1022490 (RS) or 574251
Acura	TLX	15	71	7000K	502973	VS70	707594	5514	1006938
Acura	TSX	07-14	35	1100K	502921	NO	NO	7002A or 1209	1022490 (RS) or 574590
Acura	ZDX	10-13	35	2045K	863921	NO	NO	7002A or 1214	1022490 (RS) or 574251
Alfa Romeo	4C	15	71	1100K	502921	NEW		28214	467085
Alfa Romeo	8C Competizione	09-10	35	1090K	502980	1092 or 1094	502980 or 502992	9001	545608
Audi	Allroad	02-05	35	1090K	502980	1092 or 1099L	502980 or 973120	9004	489773
Audi	A3	08-11	71	1030K	502902	NO	NO	7003 or 1053	882760 (RS) or 506565
Audi	A4	05-08	35	1090K	502980	1092	502980	9011	571724 or 574593
Audi	A4 cabrio	09	35	1090K	502980	1092	502980	9011	571724 or 574593
Audi	A4 4-door	09	71	1030K	502902	NO	NO	7003 or 1053	882760 (RS) or 506565
Audi	A5	08-09	71	1030K	502902	NO	NO	7003 or 1053	882760 (RS) or 506565
Audi	A6	05-08	35	1090K	502980	1092	502980	9011	571724 or 574593
Audi	A8	02-03	35	1090K	502980	1092	502980	9004	489773
Audi	A8	04-09	35	1090K	502980	1092	502980	9001	545608
Audi	Q5	09	71	1030K	502902	NO	NO	7003 or 1053	882760 (RS) or 506565
Audi	Q7	07-09	35	1090K	502980	1092	502980	9011	571724 or 574593
Audi	R8	08-09	35	1090K	502980	1092	502980	9011	571724 or 574593
Audi	R8	10-15	40	1096	300415	1096	300415	9011	574593
Audi	RS4	07-08	35	1090K	502980	1092	502980	9011	571724 or 574593
Audi	RS6	03	35	1090K	502980	1092	502980	9004	489773
Audi	RS7	14-15	40	1096	300415	1096	300415	9011	574593
Audi	S4	05-09	35	1090K	502980	1092	502980	9011	571724 or 574593
Audi	S5	08-09	71	1030K	502902	NO	NO	7003 or 1053	882760 (RS) or 506565
Audi	S6	07-09	35	1090K	502980	1092	502980	9011	571724 or 574593
Audi	S8	02-03	35	1090K	502980	1092	502980	9004	489773
Audi	S8	07-09	35	1090K	502980	1092	502980	9001	545608
Audi	SQ5	14-15	40	1096	300415	1096	300415	9011	574593
Audi	TT	08-10	71	1030K	502902	NO	NO	7003 or 1053	882760 (RS) or 506565
Bentley	Arnage	02-03	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	9001	545608
Bentley	Arnage	04-09	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	9011	571724 or 574593
Bentley	Azure	07-10	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	9011	571724 or 574593
Bentley	Brooklands Coupe	08-09	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	9011	571724 or 574593
Bentley	Continental GT	04-05	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	9001	545608
Bentley	Continental GT (Post May 2005)	05-10	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	9011	571724 or 574593
Bentley	Continental GT	11-15	40	1096	300415	1096	300415	9011	574593
Bentley	Flying Spur	06-10	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	9011	571724 or 574593
Bentley	Flying Spur	11-15	40	1096	300415	1096	300415	9011	574593
Bentley	Mulsanne	11-15	40	1096	300415	1096	300415	9011	574593
BMW	1 Series	08-11	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	1027	562514
BMW	1 Series (Post Sept. 2010)	11-13	40	1096	300415	1096	300415	9012	574594
BMW	2 Series	14	40	1096	300415	1096	300415	9017	728984
BMW	2 Series (Post March 2014)	14-15	71	7020K	648487	VS70	707594	5256	938131
BMW	3 Series	02-06	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	9002	573806
BMW	3 Series	07-09	35	1090K	502980	1091-1095**	502980, 502981, 502992, or 502997	1027	562514
BMW	3 Series	10-11	40	1096	300415	1096	300415	9012	574594
BMW	3 Series 2dr. and Wagon	12-13	40	1096	300415	1096	300415	9012	574594
BMW	3 Series 4dr. Sedan	12-14	40	1096	300415	1096	300415	9017	728984
BMW	3 Series (Post March 2014)	14-15	71	7020K	648487	VS70	707594	5256	938131
BMW	4 Series	14	40	1096	300415	1096	300415	9017	728984
BMW	4 Series (Post March 2014)	14-15	71	7020K	648487	VS70	707594	5256	938131
BMW	5 Series	06-11	35	1090K	502980	1091-1095	502980, 502981, 502992, or 502997	1027	562514
BMW	5 Series (Post Sept. 2010)	11-14	40	1096	300415	1096	300415	9012	574594
BMW	5 Series (Post March 2014)	15	40	1096	300415	1096	300415	9017	728984
BMW	6 Series	06-10	35	1090K	502980	1091-1095	502980, 502981, 502992, or 502997	1027	562514
BMW	6 Series	12-14	40	1096	300415	1096	300415	9012	574594
BMW	6 Series	15	40	1096	300415	1096	300415	9017	728984
BMW	7 Series	02-05	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	9002	573806
BMW	7 Series	06-11	35	1090K	502980	1091-1095	502980, 502981, 502992, or 502997	1027	562514
BMW	7 Series (Post Sept. 2010)	11-14	40	1096	300415	1096	300415	9012	574594

DILL TPMS APPLICATIONS CHART ©

Make	Model	Model Year Range	OE Torque In-Lbs	Dill Kit	Costco Kit	Valve Stem Replacement	Costco Valve	Dill/Costco	Costco
BMW	7 Series (Post March 2014)	15	40	1096	300415	1096	300415	9017	728984
BMW	I3	14-15	71	7020K	648487	VS70	707594	5256	938131
BMW	I8	14-15	71	7020K	648487	VS70	707594	5256	938131
BMW	X1	13-14	40	1096	300415	1096	300415	9012	574594
BMW	X1	15	40	1096	300415	1096	300415	9017	728984
BMW	X3	06-10	35	1090K	502980	1091-1095	502980, 502981, 502992, or 502997	1027	562514
BMW	X3	11-14	40	1096	300415	1096	300415	9012	574594
BMW	X3	15	40	1096	300415	1096	300415	9017	728984
BMW	X4	15	40	1096	300415	1096	300415	9017	728984
BMW	X5	07-11	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	1027	562514
BMW	X5 (Post Oct. 2010)	11-13	40	1096	300415	1096	300415	9012	574594
BMW	X5	14-15	71	7020K	648487	VS70	707594	5256	938131
BMW	X6	08-11	35	1090K	502980	1092-1095	502980, 502981, 502992, or 502997	1027	562514
BMW	X6 (Post Oct. 2010)	11-14	40	1096	300415	1096	300415	9012	574594
BMW	X6	15	71	7020K	648487	VS70	707594	5256	938131
BMW	Z Series	07-11	35	1090K	502980	1091-1095	502980, 502981, 502992, or 502997	1027	562514
BMW	Z Series (Post Sept. 2010)	11-14	40	1096	300415	1096	300415	9012	574594
BMW	Z4	15	40	1096	300415	1096	300415	9017	728984
**	Note: 1099 and 1099L are valve options on some special wheel packages.								
Buick	Allure	07-08	71	1050K	502904	NO	NO	7001HP	562515
Buick	Allure	09	---	VS950	502975	VS950	502975	7001HPR	562517
Buick	Enclave	08	71	1050K	502904	NO	NO	7001HP	562515
Buick	Enclave	09-14	---	VS950	502975	VS950	502975	7001HPR	562517
Buick	Enclave	15-16	---	VS20	1022467	VS20	1022467	7001HPR	562517
Buick	Encore	13-16	---	VS950	502975	VS950	502975	7001HPR	562517
Buick	LaCrosse	07-08	71	1050K	502904	NO	NO	7001HP	562515
Buick	LaCrosse	08-15	---	VS950	502975	VS950	502975	7001HPR	562517
Buick	LaCrosse	16	---	VS20	1022467	VS20	1022467	7001HPR	562517
Buick	Lesabre	07	---	VS950	502975	VS950	502975	7001HPR	562517
Buick	Lucerne	07-11	---	VS950	502975	VS950	502975	7001HPR	562517
Buick	Rainier	06-07	62	1070K	502911	NO	NO	7001HP	562515
Buick	Regal	11-15	---	VS950	502975	VS950	502975	7001HPR	562517
Buick	Regal	16	---	VS20	1022467	VS20	1022467	7001HPR	562517
Buick	Verano	12-16	---	VS950	502975	VS950	502975	7001HPR	562517
Cadillac	ATS	13	---	VS90	863920	VS90	863920	7001HPR	562517
Cadillac	ATS	14-15	---	VS950	502975	VS950	502975	7001HPR	562517
Cadillac	ATS Performance	13	62-71	7020K	648487	VS70	707594	7001HP	562515
Cadillac	ATS Performance	14-15	62	1070K	502911	NO	NO	7001HP	562515
Cadillac	CTS	04-07	62	1070K	502911	NO	NO	7001HP	562515
Cadillac	CTS	08-15	---	VS950	502975	VS950	502975	7001HPR	562517
Cadillac	CTS Vsport	14-15	62	1070K	502911	NO	NO	7001HP	562515
Cadillac	CTS-V	09-15	62	1070K	502911	NO	NO	7001HP	562515
Cadillac	Deville	01-05	62	1080K	502913	NO	NO	20117	648485
Cadillac	DTS	06	62	1070K	502911	NO	NO	7001HP	562515
Cadillac	DTS	07-11	---	VS950	502975	VS950	502975	7001HPR	562517
Cadillac	ELR	14-16	---	VS950	502975	VS950	502975	7001HPR	562517
Cadillac	Escalade-ESV-EXT	04	62	1070K	502911	NO	NO	20115	296740
Cadillac	Escalade-ESV-EXT	05-06	62	1070K	502911	NO	NO	9107	296738
Cadillac	Escalade-ESV-EXT	07	62	2020K	502931	NO	NO	7001HP	562515
Cadillac	Escalade-ESV-EXT	07	62	1070K	502911	NO	NO	7001HP	562515
Cadillac	Escalade-ESV-EXT	07-16	---	VS950	502975	VS950	502975	7001HPR	562517
Cadillac	Seville	01-04	62	1080K	502913	NO	NO	20117	648485
Cadillac	SRX	04-06	62	1070K	502911	NO	NO	7001HP	562515
Cadillac	SRX	07-16	---	VS950	502975	VS950	502975	7001HPR	562517
Cadillac	STS	05-08	62	1070K	502911	NO	NO	7001HP	562515
Cadillac	STS	09-11	---	VS950	502975	VS950	502975	7001HPR	562517
Cadillac	STS-V	09	62	1070K	502911	NO	NO	7001HP	562515
Cadillac	XLR	04-09	62	1070K	502911	NO	NO	7001HP	562515
Cadillac	XTS	13-15	---	VS950	502975	VS950	502975	7001HPR	562517
Chevrolet	Avalanche	06	62	1070K	502911	NO	NO	9107	296738
Chevrolet	Avalanche	07	62	2020K	502931	NO	NO	7001HP	562515
Chevrolet	Avalanche	07	62	1070K	502911	NO	NO	7001HP	562515
Chevrolet	Avalanche	07-13	---	VS950	502975	VS950	502975	7001HPR	562517
Chevrolet	Aveo	08-11	---	VS950	502975	VS950	502975	9153	Dealer relearn only
Chevrolet	Camaro	10-16	---	VS950	502975	VS950	502975	7001HPR	562517
Chevrolet	Camaro (sport models)	12-15	62	1070K	502911	NO	NO	7001HP	562515
Chevrolet	Caprice	11-13	62	1070K	502911	NO	NO	7001HP	562515
Chevrolet	Captiva	12-15	---	VS950	502975	VS950	502975	7001HPR	562517
Chevrolet	City Express	15	50-70	2030K	502970	NO	NO	9204	Dealer relearn only
Chevrolet	Cobalt	08-09	71	1050K	502904	NO	NO	7001HP	562515
Chevrolet	Cobalt SS	10	62	1070K	502911	NO	NO	7001HP	562515
Chevrolet	Cobalt	08-10	---	VS950	502975	VS950	502975	7001HPR	562517
Chevrolet	Colorado	07-12	62	1110K	502923	NO	NO	9131	296743
Chevrolet	Colorado	15-16	---	VS950	502975	VS950	502975	7001HPR	562517
Chevrolet	Corvette (C5)	97-00	62	1077K	845162	NO	NO	28006	296754
Chevrolet	Corvette (C5)	01-04	62	1080K	502913	NO	NO	20117	648485
Chevrolet	Corvette (C6)	05-09	62	1070K	502911	NO	NO	7001HP	562515
Chevrolet	Corvette (C6)	10-13	62	1070K	502911	NO	NO	7001HP	562515
Chevrolet	Corvette (C7)	14-15	71	1100K	502921	NEW	NEW	NEW	
Chevrolet	Cruze	11-15	---	VS950	502975	VS950	502975	7001HPR	562517
Chevrolet	Cruze	16	---	VS20	1022467	VS20	1022467	7001HPR	562517
Chevrolet	Equinox	07-09	71	1050K	502904	NO	NO	7001HP	562515
Chevrolet	Equinox	10-14	---	VS950	502975	VS950	502975	7001HPR	562517
Chevrolet	Equinox	15-16	---	VS20	1022467	VS20	1022467	7001HPR	562517
Chevrolet	Express Series	08-09	71	1050K	502904	NO	NO	7001HP	562515

DILL TPMS APPLICATIONS CHART ©

Make	Model	Model Year Range	OE Torque In-Lbs	Dill Kit	Costco Kit	Valve Stem Replacement	Costco Valve	Dill/Costco	Costco
Chevrolet	Express 1500	10-16	---	VS950	502975	VS950	502975	7001HPR	562517
Chevrolet	Express 2500/3500	10-15	---	VS950	502975	VS950	502975	7001HPR	562517
Chevrolet	G Series	08	71	1050K	502904	NO	NO	7001HP	562515
Chevrolet	HHR	08-10	62	1070K	502911	NO	NO	7001HP	562515
Chevrolet	HHR	08-11	---	VS950	502975	VS950	502975	7001HPR	562517
Chevrolet	Impala	06-07	62	1070K	502911	NO	NO	7001HP	562515
Chevrolet	Impala	07-14	---	VS950	502975	VS950	502975	7001HPR	562517
Chevrolet	Impala	14-15	---	VS950	502975	VS950	502975	7001HPR	562517
Chevrolet	Impala	16	---	VS20	1022467	VS20	1022467	7001HPR	562517
Chevrolet	Malibu (< 10/14/07)	08	71	1050K	502904	NO	NO	7001HP	562515
Chevrolet	Malibu	08-15	---	VS950	502975	VS950	502975	7001HPR	562517
Chevrolet	Malibu	16	---	VS20	1022467	VS20	1022467	7001HPR	562517
Chevrolet	Monte Carlo	05-07	62	1070K	502911	NO	NO	7001HP	562515
Chevrolet	Monte Carlo	07	---	VS950	502975	VS950	502975	7001HPR	562517
Chevrolet	Orlando	12-14	---	VS950	502975	VS950	502975	7001HPR	562517
Chevrolet	Silverado 1500	07-16	---	VS950	502975	VS950	502975	7001HPR	562517
Chevrolet	Silverado 2500/3500	07-16	---	VS950	502975	VS950	502975	7001HPR	562517
Chevrolet	Sonic	12-15	---	VS950	502975	VS950	502975	7001HPR	562517
Chevrolet	Sonic	16	---	VS20	1022467	VS20	1022467	7001HPR	562517
Chevrolet	Spark	13-15	---	VS950	502975	VS950	502975	7001HPR	562517
Chevrolet	Spark	16	---	VS20	1022467	VS20	1022467	7001HPR	562517
Chevrolet	SS sedan	14	62	1070K	502911	NO	NO	7001HP	562515
Chevrolet	Suburban	04	62	1070K	502911	NO	NO	20115	296740
Chevrolet	Suburban	05-06	62	1070K	502911	NO	NO	9107	296738
Chevrolet	Suburban 1500	07	62	2020K	502931	NO	NO	7001HP	562515
Chevrolet	Suburban 1500	07	62	1070K	502911	NO	NO	7001HP	562515
Chevrolet	Suburban 1500	07-16	---	VS950	502975	VS950	502975	7001HPR	562517
Chevrolet	Suburban 2500	07	62	2020K	502931	NO	NO	7001HP	562515
Chevrolet	Suburban 2500	07	62	1070K	502911	NO	NO	7001HP	562515
Chevrolet	Suburban 2500	07-16	---	VS950	502975	VS950	502975	7001HPR	562517
Chevrolet	Tahoe	04	62	1070K	502911	NO	NO	20115	296740
Chevrolet	Tahoe	05-06	62	1070K	502911	NO	NO	9107	296738
Chevrolet	Tahoe	07	62	2020K	502931	NO	NO	7001HP	562515
Chevrolet	Tahoe	07	62	1070K	502911	NO	NO	7001HP	562515
Chevrolet	Tahoe	07-16	---	VS950	502975	VS950	502975	7001HPR	562517
Chevrolet	Trailblazer	06-09	62	1070K	502911	NO	NO	7001HP	562515
Chevrolet	Traverse	09-14	---	VS950	502975	VS950	502975	7001HPR	562517
Chevrolet	Traverse	15-16	---	VS20	1022467	VS20	1022467	7001HPR	562517
Chevrolet	Trax	15	---	VS950	502975	VS950	502975	7001HPR	562517
Chevrolet	Uplander	08-09	62	1070K	502911	NO	NO	7001HP	562515
Chevrolet	Volt	11-15	---	VS950	502975	VS950	502975	7001HPR	562517
Chevrolet	Volt	16	---	VS20	1022467	VS20	1022467	7001HPR	562517
** Note: The 1050K is to be used on the Siemens sensors and the 1070K is to be used on the Schrader sensors.									
Chrysler	200	11-14	71	7000K	502973	VS70	707594	7001HP	562515
Chrysler	200 sedan	15	---	VS90	863920	VS90	863920	5775	863896
Chrysler	300M	02-04	35	1080K	502913	NO	NO	7004	562516
Chrysler	300	05-07	71	1050K	502904	NO	NO	7001HP	562515
Chrysler	300	08	71	1050K	502904	NO	NO	7004	562516
Chrysler	300	09	58	9066K	502970	9066K	648491	28291	296763
Chrysler	300	10-16	---	VS950	502975	VS950	502975	9398	574016
Chrysler	300C SRT8	10-14	58	9066K	502970	9066K	648491	28291	296763
Chrysler	Aspen	07-09	58	9066K	502970	9066K	648491	7001HP	562515
Chrysler	Crossfire**	04-08	35	1080K	502913	NO	NO	9028	Dealer relearn only
Chrysler	Pacifica (433 MHz)	04	35	1080K	502913	NO	NO	7004	562516
Chrysler	Pacifica (315 MHz)	04-05	71	1050K	502904	NO	NO	7001HP	562515
Chrysler	Pacifica	06-08	71	1050K	502904	NO	NO	7001HP	562515
Chrysler	Prowler	01	35	1080K	502913	NO	NO	8004	Dealer relearn only
Chrysler	Prowler	02	35	1080K	502913	NO	NO	9028	Dealer relearn only
Chrysler	PT Cruiser	08-10	71	1050K	502904	NO	NO	7001HP	562515
Chrysler	Sebring	07-10	71	1050K	502904	NO	NO	7001HP	562515
Chrysler	Sebring	10	71	7000K	502973	VS70	707594	7001HP	562515
Chrysler	Town and Country	02-03	35	1080K	502913	NO	NO	7004	562516
Chrysler	Town and Country	04-05	71	1050K	502904	NO	NO	7001HP	562515
Chrysler	Town and Country	06-07	71	1050K	502904	NO	NO	7001HP	562515
Chrysler	Town and Country	08-10	71	1050K	502904	NO	NO	7004	562516
Chrysler	Town and Country	10	71	7000K	502973	VS70	707594	7004	562516
Chrysler	Town and Country	11-16	---	VS950	502975	VS950	502975	9398	574016
** Note: An OEM Chrysler scan tool is required. A pressure change or magnet cannot be used to register 7004.									
Dodge	Avenger	08-10	71	1050K	502904	NO	NO	7001HP	562515
Dodge	Avenger	11-14	71	7000K	502973	VS70	707594	7001HP	562515
Dodge	Caliber	07-10	71	1050K	502904	NO	NO	7001HP	562515
Dodge	Caliber	11-12	71	7000K	502973	VS70	707594	7001HP	562515
Dodge	Caravan	04-05	71	1050K	502904	NO	NO	7001HP	562515
Dodge	Caravan	06	71	1050K	502904	NO	NO	7001HP	562515
Dodge	Challenger SRT8	08-14	58	9066K	502970	9066K	648491	28291	296763
Dodge	Challenger	09	58	9066K	502970	9066K	648491	28291	296763
Dodge	Challenger	10-16	---	VS950	502975	VS950	502975	9398	574016
Dodge	Challenger 6.4L V8	15-16	58	9066K	502970	9066K	648491	28291	296763
Dodge	Challenger Hellcat	15-16	58	9066K	502970	9066K	648491	28291	296763
Dodge	Charger	06-07	71	1050K	502904	NO	NO	7001HP	562515
Dodge	Charger	08	71	1050K	502904	NO	NO	7004	562516
Dodge	Charger	09	58	9066K	502970	9066K	648491	28291	296763
Dodge	Charger SRT8	10-14	58	9066K	502970	9066K	648491	28291	296763
Dodge	Charger	10-16	---	VS950	502975	VS950	502975	9398	574016
Dodge	Charger 6.4L V8	15-16	58	9066K	502970	9066K	648491	28291	296763
Dodge	Charger Hellcat	15-16	58	9066K	502970	9066K	648491	28291	296763
Dodge	Dakota	08-10	58	9066K	502970	9066K	648491	7001HP	562515
Dodge	Dakota	11	---	VS950	502975	VS950	502975	7001HPR	562517
Dodge	Dart	13-16	---	VS90	863920	VS90	863920	5775	863896

DILL TPMS APPLICATIONS CHART ©

Make	Model	Model Year Range	OE Torque In-Lbs	Dill Kit	Costco Kit	Valve Stem Replacement	Costco Valve	Dill/Costco	Costco
Dodge	Durango	07-09	58	9066K	502970	9066K	648491	7001HP	562515
Dodge	Durango	11-15	---	VS950	502975	VS950	502975	9398	574016
Dodge	Grand Caravan	02-03	35	1080K	502913	NO	NO	7004	562516
Dodge	Grand Caravan	04-05	71	1050K	502904	NO	NO	7001HP	562515
Dodge	Grand Caravan	06-07	71	1050K	502904	NO	NO	7001HP	562515
Dodge	Grand Caravan	08-10	71	1050K	502904	NO	NO	7004	562516
Dodge	Grand Caravan	10	71	7000K	502973	VS70	707594	7004	562516
Dodge	Grand Caravan	11-16	---	VS950	502975	VS950	502975	9398	574016
Dodge	Journey	09-10	71	1050K	502904	NO	NO	7004	562516
Dodge	Journey	11-16	---	VS950	502975	VS950	502975	9398	574016
Dodge	Magnum	05-07	71	1050K	502904	NO	NO	7001HP	562515
Dodge	Magnum	08	71	1050K	502904	NO	NO	7004	562516
Dodge	Nitro	07-09	58	9066K	502970	9066K	648491	7001HP	562515
Dodge	Nitro	10-11	---	VS950	502975	VS950	502975	7001HPR	562517
Dodge	Ram C/V	12-15	---	VS950	502975	VS950	502975	9398	574016
Dodge	Ram Promaster	14-16	71	1100K	502921	NEW		28214	467085
Dodge	Ram Promaster City	15	71	1100K	502921	NEW		28214	467085
Dodge	Ram 1500	08	58	9066K	502970	9066K	648491	28154	296757
Dodge	Ram 2500	08-09	58	9066K	502970	9066K	648491	7001HP	562515
Dodge	Ram 1500	09	71	1050K	502904	NO	NO	7004	562516
Dodge	Ram	10-13	---	VS950	502975	VS950	502975	9398	574016
Dodge	Ram (4-wheel)	14-15	---	VS65	938120	VS65	938120	6815	863898
Dodge	Ram 3500 (6-wheel) Outer Steel Wheel Sensor	14-15	---	VS65	938120	VS65	938120	6815	863898
Dodge	Ram 3500 (6-wheel) Outer Alloy Wheel Sensor	14-15	80-125	VS35	938121	VS35	938121	6829	752311
Dodge	Ram 3500 (6-wheel) Inner Rear Wheel Sensor	14-15	---	VS65	938120	VS65	938120	6825	752304
Dodge	Sprinter	07-10	54	1098K	503006	1098K	503006	1042	574595
Dodge	Viper**	03-10	35	1080K	502913	NO	NO	9028	Dealer relearn only
Dodge	SRT Viper	13-16	58	9066K	502970	9066K	648491	28291	296763
** Note: An OEM Dodge scan tool is required. A pressure change or magnet cannot be used to register 7004.									
Ferrari	360	04-05	35	1090K	502980	1092 or 1094	502980 or 502992	9001	545608
Ferrari	F430	05-07	35	1090K	502980	1092	502980	9001	545608
Ferrari	F430 (Post July 2007)	07-09	35	1090K	502980	1092	502980	9011	571724 or 574593
Ferrari	458	10-15	40	1096	300415	1096	300415	9011	574593
Ferrari	575M (433 MHz)	02-05	35	1090K	502980	1092	502980	9001	545608
Ferrari	575M (315 MHz)	02-05	35	1090K	502980	1092	502980	9004	489773
Ferrari	599	07-11	35	1090K	502980	1092	502980	9001	545608
Ferrari	612 Scaglietta	05-10	35	1090K	502980	1092	502980	9001	545608
Ferrari	California	09-10	35	1090K	502980	1092	502980	9011	574587 or 574593
Ferrari	California	11-15	40	1096	300415	1096	300415	9011	574593
Ferrari	Enzo	03-05	35	1090K	502980	1092	502980	9005	574094
Ferrari	F12berlinetta	13-15	40	1096	300415	1096	300415	9011	574593
Ferrari	FF	12-15	40	1096	300415	1096	300415	9011	574593
Ferrari	FX	05-06	35	1090K	502980	1092	502980	9005	574094
Fiat	500	12-15	---	VS950	502975	VS950	502975	9398	574016
Fiat	500L	14-15	---	VS950	502975	VS950	502975	9398	574016
Fiat	500X	15	---	VS90	863920	VS90	863920	5775	863896
Fisker	Karma	10-12	---	VS1010	502976	VS1010	502976		
Ford	C-Max	13-15	---	VS950	502975	VS950	502975	7001HPR	562517
Ford	Crown Victoria	08-11	---	band	1194 band	NO	NO	7001HPR	562517
Ford	E Series	08-09	---	band	1194 band	NO	NO	7001HPR	562517
Ford	E-250 van	08-09	---	band	1194 band	NO	NO	7001HPR	562517
Ford	E Series	10-14	---	VS950	502975	VS950	502975	7001HPR	562517
Ford	Edge	07-10	---	band	1194 band	NO	NO	7001HPR	562517
Ford	Edge	11-14	---	VS950	502975	VS950	502975	7001HPR	562517
Ford	Edge	15-16	---	VS20	1022467	VS20	1022467	9280	1006942
Ford	Escape	05-08	---	band	1194 band	NO	NO	7001HPR	562517
Ford	Escape	09-16	---	VS950	502975	VS950	502975	7001HPR	562517
Ford	Expedition	03-04	44	1060K	502905	NO	NO	7004	562516
Ford	Expedition	05-06	44	1060K	502905	NO	NO	7001HP	562515
Ford	Expedition	07-10	---	band	1194 band	NO	NO	7001HPR	562517
Ford	Expedition	11-16	---	VS950	502975	VS950	502975	7001HPR	562517
Ford	Explorer	02-05	44	1060K	502905	NO	NO	7004	562516
Ford	Explorer Sport Trac	07-10	---	band	1194 band	NO	NO	7001HPR	562517
Ford	Explorer	06-10	---	band	1194 band	NO	NO	7001HPR	562517
Ford	Explorer	11-15	---	VS950	502975	VS950	502975	7001HPR	562517
Ford	Explorer	16	---	VS20	1022467	VS20	1022467	9280	1006942
Ford	F-150 (Light Duty)	07-08	---	band	1194 band	NO	NO	7001HPR	562517
Ford	F-150 (Heavy Duty)	07-08	---	band	1194 band	NO	NO	7001HPR	562517
Ford	F-150	09-14	---	VS950	502975	VS950	502975	7001HPR	562517
Ford	F-150	15-16	---	VS20	1022467	VS20	1022467	9280	1006942
Ford	F-250 / F-350	08-09	---	band	1194 band	NO	NO	7001HPR	562517
Ford	F-250 / F-350	10-16	---	VS950	502975	VS950	502975	7001HPR	562517
Ford	Fiesta	11-16	---	VS950	502975	VS950	502975	7001HPR	562517
Ford	Flex	09-10	---	band	1194 band	NO	NO	7001HPR	562517
Ford	Flex	11-15	---	VS950	502975	VS950	502975	7001HPR	562517
Ford	Focus	08-09	---	band	1194 band	NO	NO	7001HPR	562517
Ford	Focus	10-15	---	VS950	502975	VS950	502975	7001HPR	562517
Ford	Freestar	06-07	---	band	1194 band	NO	NO	7001HPR	562517
Ford	Fusion	08-09	---	band	1194 band	NO	NO	7001HPR	562517
Ford	Fusion	10-16	---	VS950	502975	VS950	502975	7001HPR	562517
Ford	Mustang	07-09	---	band	1194 band	NO	NO	7001HPR	562517
Ford	Mustang	10-14	---	VS950	502975	VS950	502975	7001HPR	562517
Ford	Mustang	15	---	VS20	1022467	VS20	1022467	9280	1006942
Ford	Police Interceptor sedan	13-16	---	VS950	502975	VS950	502975	7001HPR	562517
Ford	Police Interceptor Utility	13-14	---	VS950	502975	VS950	502975	7001HPR	562517
Ford	Ranger	07-11	---	band	1194 band	NO	NO	7001HPR	562517

DILL TPMS APPLICATIONS CHART ©

Make	Model	Model Year Range	OE Torque In-Lbs	Dill Kit	Costco Kit	Valve Stem Replacement	Costco Valve	Dill/Costco	Costco
Ford	Shelby GT	13-14	---	VS925C		VS925C		7001HPR	562517
Ford	Super Duty	08-09	---	band	1194 band	NO	NO	7001HPR	562517
Ford	Super Duty	10-16	---	VS950	502975	VS950	502975	7001HPR	562517
Ford	Taurus	08-10	---	band	1194 band	NO	NO	7001HPR	562517
Ford	Taurus	11-15	---	VS950	502975	VS950	502975	7001HPR	562517
Ford	Taurus X	08-09	---	band	1194 band	NO	NO	7001HPR	562517
Ford	Transit Connect	10-15	---	VS950	502975	VS950	502975	7001HPR	562517
Ford	Transit (SRW)	15	---	VS950	502975	VS950	502975	7001HPR	562517
** Note: Redi-Sensor relearn must be performed with a scan tool, not a magnet.									
GMC	Acadia	07-08	71	1050K	502904	NO	NO	7001HP	562515
GMC	Acadia	09-14	---	VS950	502975	VS950	502975	7001HPR	562517
GMC	Acadia	15	---	VS20	1022467	VS20	1022467	7001HPR	562517
GMC	Canyon	07-12	62	1110K	502923	NO	NO	9131	296743
GMC	Canyon	15	---	VS950	502975	VS950	502975	7001HPR	562517
GMC	Envoy	06-09	62	1070K	502911	NO	NO	7001HP	562515
GMC	Savana	08-09	71	1050K	502904	NO	NO	7001HP	562515
GMC	Savana	10-15	---	VS950	502975	VS950	502975	7001HPR	562517
GMC	Sierra 1500	07-15	---	VS950	502975	VS950	502975	7001HPR	562517
GMC	Sierra 2500/3500	07-15	---	VS950	502975	VS950	502975	7001HPR	562517
GMC	Terrain	10-14	---	VS950	502975	VS950	502975	7001HPR	562517
GMC	Terrain	15	---	VS20	1022467	VS20	1022467	7001HPR	562517
GMC	Yukon (all)	04	62	1070K	502911	NO	NO	20115	296740
GMC	Yukon (all)	05-06	62	1070K	502911	NO	NO	9107	296738
GMC	Yukon	07	62	2020K	502931	NO	NO	7001HP	562515
GMC	Yukon	07	62	1070K	502911	NO	NO	7001HP	562515
GMC	Yukon	07-15	---	VS950	502975	VS950	502975	7001HPR	562517
GMC	Yukon 2500	07	62	2020K	502931	NO	NO	7001HP	562515
GMC	Yukon 2500	07	62	1070K	502911	NO	NO	7001HP	562515
GMC	Yukon 2500	07-13	---	VS950	502975	VS950	502975	7001HPR	562517
Honda	Accord	08-12	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Honda	Civic	08-14	35	2045K	863921	NO	NO	7002 or 7002A	707597 or 1022490
Honda	CR-V	07-11	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Honda	CR-V	12-13	71	7020K	648487	VS70	707594	7002 or 7002A	707597 or 1022490
Honda	CR-Z	11-15	35	2045K	863921	NO	NO	7002 or 7002A	707597 or 1022490
Honda	Crosstour	10-15	71	7020K	648487	VS70	707594	7002 or 7002A	707597 or 1022490
Honda	Element	07-08	40	2000K	300415	1096	300415	7002 or 7002A	707597 or 1022490
Honda	Element	09-11	35	2045K	863921	NO	NO	7002 or 7002A	707597 or 1022490
Honda	Fit	08	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Honda	Fit	09-14	35	2045K	863921	NO	NO	7002 or 7002A	707597 or 1022490
Honda	Insight	10-14	35	2045K	863921	NO	NO	7002 or 7002A	707597 or 1022490
Honda	Odyssey EX, EX-L, LX	07	40	2000K	300415	1096	300415	7002 or 7002A	707597 or 1022490
Honda	Odyssey EX, EX-L, LX	08-10	35 or 40	2045K	863921	NO	NO	7002 or 7002A	707597 or 1022490
Honda	Odyssey Touring	05-07	40	2000K	300415	1096	300415	7002A or 1057	1022490 (RS) or 503013
Honda	Odyssey Touring	08-10	35 or 40	2045K	863921	NO	NO	7002A or 1057	1022490 (RS) or 503013
Honda	Odyssey and Touring	11-16	35	2045K	863921	NO	NO	7002 or 7002A	707597 or 1022490
Honda	Pilot (Steel Wheels)	05-08	40	2000K	300414	1097	300414	7002A or 1059	1022490 (RS) or 518211
Honda	Pilot (Alloy Wheels)	05-08	40	2000K	300415	1096	300415	7002A or 1057	1022490 (RS) or 503013
Honda	Pilot (Alloy Wheels)	09-15	35	1100K	502921	NO	NO	7002A or 1209	1022490 (RS) or 574590
Honda	Pilot (Steel Wheels)	09-15	35	1100K	502921	NO	NO	7002A or 1219	1022490
Honda	Ridgeline (Steel Wheels)	06-08	40	2000K	300414	1097	300414	7002A or 1059	1022490 (RS) or 518211
Honda	Ridgeline (Alloy Wheels)	06-08	40	2000K	300415	1096	300415	7002A or 1057	1022490 (RS) or 503013
Honda	Ridgeline	09-14	35 or 40	2045K	863921	NO	NO	7002A or 1057	1022490 (RS) or 503013
Honda	S2000	08-09	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Hummer	H2	08-09	---	VS950	502975	VS950	502975	7001HPR	562517
Hummer	H3	06-10	62	1110K	502923	NO	NO	9131	296743
Hummer	H3T	09-10	62	1110K	502923	NO	NO	9131	296743
Hyundai	Accent	08-11	31-40	2040K	502971	NO	NO	7002 or 7002A	707597 or 1022490
Hyundai	Accent	12-13	71	7020K	648487	VS70	707594	7001HP	562515
Hyundai	Accent	14	71	7020K	648487	VS70	707594	5508	1006664
Hyundai	Accent	15	71	7020K	648487	VS70	707594	5510	973097
Hyundai	Azera	07-11	40	2000K	300415	1096	300415	7002 or 7002A	707597 or 1022490
Hyundai	Azera	12-15	35	2040K	502971	VS965	707626	1233	972680
Hyundai	Elantra	08-10	40	2000K	300415	1096	300415	7002 or 7002A	707597 or 1022490
Hyundai	Elantra	11-13	35	2040K	502971	VS965	707626	7002 or 7002A	707597 or 1022490
Hyundai	Elantra (Post Nov. 2013)	13-16	35	2040K	502971	VS965	707626	NEW	
Hyundai	Elantra Touring	09-12	71	1050K or 7020K		VS70	707594	7001HP	562515
Hyundai	Elantra GT	13-16	71	7020K	648487	VS70	707594	5508	1006664
Hyundai	Entourage	07-09	40	2000K	300415	1096	300415	1028	518217
Hyundai	Equus	11-13	31-40	2040K	502971	NO	NO	7002A or 1029	1022490 (RS) or 854696
Hyundai	Equus	14-16	71	7020K	648487	VS70	707594	5508	1006664
Hyundai	Genesis Sedan	09-13	31-40	2040K	502971	NO	NO	7002A or 1029	1022490 (RS) or 854696
Hyundai	Genesis Sedan	14-15	71	7020K	648487	VS70	707594	5510	973097
Hyundai	Genesis Coupe	10-12	71	7020K	648487	VS70	707594	7001HP	562515
Hyundai	Genesis Coupe	13-15	71	7020K	648487	VS70	707594	5508	1006664
Hyundai	Santa Fe	07-08	40	2000K	300415	1096	300415	1028	518217
Hyundai	Santa Fe	09	40	2000K	300415	1096	300415	7002 or 7002A	707597 or 1022490
Hyundai	Santa Fe	10-12	11	VS1010	502976	VS1010	502976	7002 or 7002A	707597 or 1022490
Hyundai	Santa Fe	13-16	71	7020K	648487	VS70	707594	5508	1006664
Hyundai	Sonata	07-08	40	2000K	300415	1096	300415	7002A or 1058	1022490 (RS) or 518214
Hyundai	Sonata	09-10	31-40	2040K	502971	NO	NO	7002 or 7002A	707597 or 1022490
Hyundai	Sonata	11-12	71	7020K	648487	VS70	707594	7001HP	562515
Hyundai	Sonata	13-14	71	7020K	648487	VS70	707594	5508	1006664
Hyundai	Sonata Hybrid	15	71	7020K	648487	VS70	707594	5508	1006664
Hyundai	Sonata (non-hybrid)	15	---	VS20	1022467	VS20	1022467	NEW	
Hyundai	Sonata	16	---	VS20	1022467	VS20	1022467	NEW	

DILL TPMS APPLICATIONS CHART ©

Make	Model	Model Year Range	OE Torque In-Lbs	Dill Kit	Costco Kit	Valve Stem Replacement	Costco Valve	Dill/Costco	Costco
Hyundai	Tiburon	07-08	40	2000K	300415	1096	300415	7002A or 1058	1022490 (RS) or 518214
Hyundai	Tucson	06-07	40	2000K	300415	1096	300415	7002A or 1058	1022490 (RS) or 518214
Hyundai	Tucson	08-10	40	2000K	300415	1096	300415	7002A or 1058	1022490 (RS) or 518214
Hyundai	Tucson	10-13	31-40	2040K	502971	NO	NO	7002 or 7002A	707597 or 1022490
Hyundai	Tucson	14-15	35	2040K	502971	VS965	707626	NEW	
Hyundai	Tucson	16	---	VS20	1022467	VS20	1022467	NEW	
Hyundai	Veloster	12-16	---	VS950	502975	VS950	502975	9505	
Hyundai	Veracruz	07-08	40	2000K	300415	1096	300415	1028	518217
Hyundai	Veracruz	09-12	40	2000K	300415	1096	300415	7002 or 7002A	707597 or 1022490
Infiniti	EX	08-10	35	1100K	502921	NO	NO	7001HP	562515
Infiniti	EX	11-13	35	1100K	502921	NO	NO	7003 or 1216	882760 (RS) or 643321
Infiniti	FX	03-07	45-60	1080K	502913	NO	NO	7001HP	562515
Infiniti	FX (Post June 2007)	08	66	2030K	502970	NO	NO	7001HP	562515
Infiniti	FX (Post June 2008)	09-10	35	1100K	502921	NO	NO	7001HP	562515
Infiniti	FX (Post March 2010)	10-13	35	1100K	502921	NO	NO	7003 or 1216	882760 (RS) or 643321
Infiniti	G35	04-07	45-60	1080K	502913	NO	NO	7001HP	562515
Infiniti	G35 Coupe (Post Aug. 2006)	07	66	2030K	502970	NO	NO	7001HP	562515
Infiniti	G35 Sedan	07	35	1100K	502921	NO	NO	7001HP	562515
Infiniti	G	08-10	35	1100K	502921	NO	NO	7001HP	562515
Infiniti	G (Post March 2010)	10-13	35	1100K	502921	NO	NO	7003 or 1216	882760 (RS) or 643321
Infiniti	JX	13	71	7020K	648487	VS70	707594	5556	863892
Infiniti	M	03-07	45-60	1080K	502913	NO	NO	7001HP	562515
Infiniti	M	08-10	66	2030K	502970	NO	NO	7001HP	562515
Infiniti	M (Post March 2010)	10-13	35	1100K	502921	NO	NO	7003 or 1216	882760 (RS) or 643321
Infiniti	Q45	03-06	45-60	1080K	502913	NO	NO	7001HP	562515
Infiniti	Q40	15	35	1100K	502921	NO	NO	7003 or 1216	882760 (RS) or 643321
Infiniti	Q50	14-15	71	7020K	648487	VS70	707594	5558	939241
Infiniti	Q60	14-15	35	1100K	502921	NO	NO	7003 or 1216	882760 (RS) or 643321
Infiniti	Q70	14-15	35	1100K	502921	NO	NO	7003 or 1216	882760 (RS) or 643321
Infiniti	QX50	14-15	35	1100K	502921	NO	NO	7003 or 1216	882760 (RS) or 643321
Infiniti	QX56	04-07	49	1080K	502913	NO	NO	7001HP	562515
Infiniti	QX56	08-10	66	2030K	502970	NO	NO	7001HP	562515
Infiniti	QX56 (Post March 2010)	10	35	1100K	502921	NO	NO	7003 or 1216	882760 (RS) or 643321
Infiniti	QX56	11-13	35	1100K	502921	NO	NO	1216	643321
Infiniti	QX60	14-15	71	7020K	648487	VS70	707594	5556	863892
Infiniti	QX70	14	35	1100K	502921	NO	NO	7003 or 1216	882760 (RS) or 643321
Infiniti	QX70	15	35	1100K	502921	NO	NO	1216	643321
Infiniti	QX80	14-15	35	1100K	502921	NO	NO	1216	643321
ITEC	Trucks(433 Mhz)	all	---	VS9013 or VS9980		VS9013 or VS9980		9010	
Isuzu	Ascender	06-08	62	1070K	502911	NO	NO	7001HP	562515
Isuzu	I-290	07-08	62	1110K	502923	NO	NO	9131	296743
Isuzu	I-370	07-08	62	1110K	502923	NO	NO	9131	296743
Isuzu	Rodeo	04	35	1080K	502913	NO	NO	9028	Dealer relearn only
Jaguar	F-Type (315 MHz)	14	71	7020K	648487	VS70	707594	1045	643315
Jaguar	F-Type (433 MHz Export)	14	71	1050K	502904	NO	NO	1046	574421
Jaguar	Super V8 (315 MHz)	05-09	71	1050K	502904	NO	NO	1055	503011
Jaguar	Super V8 (433MHz Export)	05-09	71	1050K	502904	NO	NO	1046	574421
Jaguar	Vanden Plas (315 MHz)	04-09	71	1050K	502904	NO	NO	1055	503011
Jaguar	Vanden Plas (433MHz Export)	04-09	71	1050K	502904	NO	NO	1046	574421
Jaguar	X-Type (315 MHz)	08	71	1050K	502904	NO	NO	1055	503011
Jaguar	X-Type (433MHz Export)	08	71	1050K	502904	NO	NO	1046	574421
Jaguar	XF (315 MHz)	09-10	71	1050K	502904	NO	NO	1055	503011
Jaguar	XF (433MHz Export)	09-10	71	1050K	502904	NO	NO	1046	574421
Jaguar	XF (315 MHz)	11-15	71	1050K	502904	NO	NO	1055	503011
Jaguar	XF (433 MHz Export)	11-14	71	1050K	502904	NO	NO	1046	574421
Jaguar	XJ (315 MHz)	06-09	71	1050K	502904	NO	NO	1055	503011
Jaguar	XJ (433MHz Export)	06-09	71	1050K	502904	NO	NO	1046	574421
Jaguar	XJ (315 MHz)	10-11	71	1050K	502904	NO	NO	1055	503011
Jaguar	XJ (433MHz Export)	10-11	71	1050K	502904	NO	NO	1046	574421
Jaguar	XJ (315 MHz)	12-14	71	7020K	648487	VS70	707594	1045	643315
Jaguar	XJ (433 MHz Export)	12-14	71	1050K	502904	NO	NO	1046	574421
Jaguar	XK (315 MHz)	07-09	71	1050K	502904	NO	NO	1055	503011
Jaguar	XK (433MHz Export)	07-09	71	1050K	502904	NO	NO	1046	574421
Jaguar	XK (315 MHz)	10-14	71	1050K	502904	NO	NO	1055	503011
Jaguar	XK (433 MHz Export)	10-14	71	1050K	502904	NO	NO	1046	574421
Jeep	Cherokee	14-15	---	VS65	938120	VS65	938120	6815	863898
Jeep	Commander	06	71	1050K	502904	NO	NO	7001HP	562515
Jeep	Commander	07	58	9066K	502970	9066K	648491	7001HP	562515
Jeep	Commander	08-10	58	9066K	502970	9066K	648491	7004	562516
Jeep	Compass	07-10	71	1050K	502904	NO	NO	7001HP	562515
Jeep	Compass	11-12	71	7000K	502973	VS70	707594	7001HP	562515
Jeep	Compass	13-15	---	VS950	502975	VS950	502975	7001HPR	562517
Jeep	Compass (433MHz Export)	13-14	---	VS950	502975	VS950	502975	9481	643371
Jeep	Grand Cherokee	02-04	64	1080K	502913	NO	NO	7004	562516
Jeep	Grand Cherokee	05-06	71	1050K	502904	NO	NO	7001HP	562515
Jeep	Grand Cherokee	07	58	9066K	502970	9066K	648491	7001HP	562515
Jeep	Grand Cherokee	08-10	58	9066K	502970	9066K	648491	7004	562516
Jeep	Grand Cherokee	11-15	---	VS950	502975	VS950	502975	9398	574016
Jeep	Grand Cherokee SRT8	12-15	58	9066K	502970	9066K	648491	28291	296763
Jeep	Liberty	04	64	1080K	502913	NO	NO	7004	562516
Jeep	Liberty	05-06	71	1050K	502904	NO	NO	7001HP	562515
Jeep	Liberty	07-10	58	9066K	502970	9066K	648491	7001HP	562515
Jeep	Liberty	10-12	---	VS950	502975	VS950	502975	7001HPR	562517
Jeep	Liberty (433MHz Export)	07-09	58	9066K	502970	9066K	648491	7004	562516
Jeep	Liberty (433MHz Export)	10-12	---	VS950	502975	VS950	502975	9481	643371
Jeep	Patriot	07-10	71	1050K	502904	NO	NO	7001HP	562515
Jeep	Patriot	11-12	71	7000K	502973	VS70	707594	7001HP	562515
Jeep	Patriot	13-15	---	VS950	502975	VS950	502975	7001HPR	562517

DILL TPMS APPLICATIONS CHART ©

Make	Model	Model Year Range	OE Torque In-Lbs	Dill Kit	Costco Kit	Valve Stem Replacement	Costco Valve	Dill/Costco	Costco
Jeep	Patriot (433MHz Export)	12-14	---	VS950	502975	VS950	502975	9481	643371
Jeep	Renegade	15	---	VS90	863920	VS90	863920	5775	863896
Jeep	Wrangler	07-10	58	9066K	502970	9066K	648491	7001HP	562515
Jeep	Wrangler (433MHz Export)	08-10	58	9066K	502970	9066K	648491	7004	562516
Jeep	Wrangler	10-12	---	VS950	502975	VS950	502975	7001HPR	562517
Jeep	Wrangler (433MHz Export)	10-12	---	VS950	502975	VS950	502975	9481	643371
Jeep	Wrangler	13-16	---	VS950	502975	VS950	502975	9398	574016
** Note: The 1050K is to be used on the Siemens sensors and the 9066K or 2030K is to be used on the Schrader sensors.									
KIA	Amanti	07-08	40	2000K	300415	1096	300415	7002A or 1058	1022490 (RS) or 518214
KIA	Amanti	09	40	2000K	300415	1096	300415	7002A or 1058	1022490 (RS) or 518214
KIA	Borrego	09-11	31-40	2040K	502971	NO	NO	7002 or 7002A	707597 or 1022490
KIA	Cadenza	14-15	71	7020K	648487	VS70	707594	5508	1006664
KIA	Forte	10-13	71	7020K	648487	VS70	707594	7001HP	562515
KIA	Forte	14-15	35	2040K	502971	VS965	707626	NEW	
KIA	Magentis	08-10	40	2000K	300415	1096	300415	7002 or 7002A	707597 or 1022490
KIA	Optima	06-10	40	2000K	300415	1096	300415	7002 or 7002A	707597 or 1022490
KIA	Optima	11-13	71	7020K	648487	VS70	707594	7001HP	562515
KIA	Optima	14-15	71	7020K	648487	VS70	707594	5508	1006664
KIA	Rio	08-11	31-40	2040K	502971	NO	NO	7002 or 7002A	707597 or 1022490
KIA	Rio	12-16	35	2040K	502971	VS965	707626	7002A	1022490
KIA	Rondo	07-10	40	2000K	300415	1096	300415	7002 or 7002A	707597 or 1022490
KIA	Sedona	06-08	40	2000K	300415	1096	300415	1028	518217
KIA	Sedona	09-14	40	2000K	300415	1096	300415	7002 or 7002A	707597 or 1022490
KIA	Sedona	15-16	---	VS20	1022467	VS20	1022467	NEW	
KIA	Sorento (with tire display)	07-08	40	2000K	300415	1096	300415	7002A or 1058	1022490 (RS) or 518214
KIA	Sorento (without tire display)	08-09	40	2000K	300415	1096	300415	7002A or 1058	1022490 (RS) or 518214
KIA	Sorento	11-13	71	7020K	648487	VS70	707594	7001HP	562515
KIA	Sorento	14-15	71	7020K	648487	VS70	707594	5508	1006664
KIA	Sorento	16	71	7020K	648487	VS70	707594	5510	973097
KIA	Soul	10-13	71	7020K	648487	VS70	707594	7001HP	562515
KIA	Soul	14-16	---	VS20	1022467	VS20	1022467	NEW	
KIA	Spectra	07-09	31-40	2040K	502971	NO	NO	7002 or 7002A	707597 or 1022490
KIA	Sportage	06-08	40	2000K	300415	1096	300415	7002A or 1058	1022490 (RS) or 518214
KIA	Sportage	09-13	31-40	2040K	502971	NO	NO	7002 or 7002A	707597 or 1022490
KIA	Sportage	14-15	35	2040K	502971	VS965	707626	NEW	
Lamborghini	Aventador	12-15	40	1096	300415	1096	300415	9011	574593
Lamborghini	Gallardo	08-14	35-40	1096	300415	1096	300415	9011	574593
Lamborghini	Huracan	15	40	1096	300415	1096	300415	9011	574593
Lamborghini	Murcielago	08-10	40	1096	300415	1096	300415	9011	574593
Land Rover	Discovery Sport	15	71	7020K	648487	VS70	707594	5328	
Land Rover	Evoque (315 MHz)**	12-14	71	7020K	648487	VS70	707594	1045**	643315
Land Rover	Evoque (433 MHz)**	14-15	71	7020K	648487	VS70	707594	5328**	
Land Rover	LR2	08-10	71	1050K	502904	NO	NO	1045	643315
Land Rover	LR2	10-15	71	7020K	648487	VS70	707594	1045	643315
Land Rover	LR3	06-09	71	1050K	502904	NO	NO	1055	503011
Land Rover	LR4 (315 MHz)**	10-14	71	7020K	648487	VS70	707594	1045**	643315
Land Rover	LR4 (433 MHz)**	13-15	71	7020K	648487	VS70	707594	5328**	
Land Rover	Range Rover	03-05	35	1090K	502980	1092	502980	9003	661042
Land Rover	Range Rover	06-09	71	1050K	502904	NO	NO	1055	503011
Land Rover	Range Rover (315 MHz)**	10-14	71	7020K	648487	VS70	707594	1045**	643315
Land Rover	Range Rover (433 MHz)**	14-15	71	7020K	648487	VS70	707594	5328**	
Land Rover	Range Rover Sport	06-09	71	1050K	502904	NO	NO	1055	503011
Land Rover	Range Rover Sport (315 MHz)**	10-14	71	7020K	648487	VS70	707594	1045**	643315
Land Rover	Range Rover Sport (433 MHz)**	14-15	71	7020K	648487	VS70	707594	5328**	
** Note: Utilize the VIN on MY 2013 - 14 vehicles in determining the correct sensor frequency.									
Lexus	CT200h	11-15	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Lexus	ES	07-12	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Lexus	ES**	13-15	35	1100K	502921	NO	NO	1218	643351
Lexus	GS	06-11	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Lexus	GS**	13-15	35	1100K	502921	NO	NO	1218	643351
Lexus	GX	03-06	35	1100K	502923	NO	NO	7002* or 7002A*	707597* or 1022490*
Lexus	GX	07-09	35	1100K	502921	NO	NO	7002* or 7002A*	707597* or 1022490*
Lexus	GX	10-15	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Lexus	HS250h	10-12	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Lexus	IS	06-13	35	1100K	502921	NO	NO	7002* or 7002A*	707597* or 1022490*
Lexus	IS250 / IS350 4dr.**	14-15	35	1100K	502921	NO	NO	1218	643351
Lexus	IS C	14-15	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Lexus	IS F	14	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Lexus	LFA	11-13	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Lexus	LS	07-12	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Lexus	LS**	13-15	35	1100K	502921	NO	NO	1218	643351
Lexus	LX	06-15	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Lexus	NX**	15	35	1100K	502921	NO	NO	1218	643351
Lexus	RC and RC-F**	15	35	1100K	502921	NO	NO	1218	643351
Lexus	RX	07-14	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Lexus	RX (made in Canada)	15	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Lexus	RX (made in Japan)	15	35	1100K	502921	NO	NO	1230	
Lexus	SC430**	02-06	27	1120K	502924	NO	NO		Dealer relearn only
Lexus	SC 430	07-10	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
* Note: 406K is needed if the valve hole's counterbore diameter is small than a US dime coin (0.70in).									
** Note: Dealer tool is required for the relearn.									
Lincoln	Aviator	03-05	44	1060K	502905	NO	NO	7004	562516
Lincoln	Mark LT	07-08	---	band	1194 band	NO	NO	7001HPR	562517
Lincoln	MKC	15	---	VS950	502975	VS950	502975	7001HPR	562517
Lincoln	MKS	09-10	---	band	1194 band	NO	NO	7001HPR	562517
Lincoln	MKS	11-15	---	VS950	502975	VS950	502975	7001HPR	562517
Lincoln	MKT	10-10	---	band	1194 band	NO	NO	7001HPR	562517
Lincoln	MKT	11-15	---	VS950	502975	VS950	502975	7001HPR	562517
Lincoln	MX	07-10	---	band	1194 band	NO	NO	7001HPR	562517

DILL TPMS APPLICATIONS CHART ©

Make	Model	Model Year Range	OE Torque In-Lbs	Dill Kit	Costco Kit	Valve Stem Replacement	Costco Valve	Dill/Costco	Costco
Lincoln	MX	11-15	---	VS950	502975	VS950	502975	7001HPR	562517
Lincoln	MX	16	---	VS20	1022467	VS20	1022467	9280	1006942
Lincoln	MKZ	08-09	---	band	1194 band	NO	NO	7001HPR	562517
Lincoln	MKZ	10-15	---	VS950	502975	VS950	502975	7001HPR	562517
Lincoln	Navigator	03-04	44	1060K	502905	NO	NO	7004	562516
Lincoln	Navigator	05-06	44	1060K	502905	NO	NO	7001HP	562515
Lincoln	Navigator	07-10	---	band	1194 band	NO	NO	7001HPR	562517
Lincoln	Navigator	11-15	---	VS950	502975	VS950	502975	7001HPR	562517
Lincoln	Town Car	08-11	---	band	1194 band	NO	NO	7001HPR	562517
** Note: Redi-Sensor relearn must be performed with a scan tool, not a magnet.									
Lotus	Elise	08-11	44	2010K	502930	NO	NO	9159	1006949
Lotus	Evora	10-14	44	2010K	502930	NO	NO	9159	1006949
Lotus	Exige	08-11	44	2010K	502930	NO	NO	9159	1006949
Maserati	Coupe	05-06	35	1090K	502980	1092 or 1094	502980 or 502992	9001	545608
Maserati	Gran Turismo	08-10	35	1090K	502980	1092	502980	9001	545608
Maserati	Gran Turismo	11-14	40	1096	300415	1096	300415	9011	574593
Maserati	Ghibli	14	71	1100K	502921	NEW	NEW	NEW	
Maserati	Quattroporte	05-10	35	1090K	502980	1092	502980	9001	545608
Maserati	Quattroporte	11-13	40	1096	300415	1096	300415	9011	574593
Maserati	Quattroporte	14	71	1100K	502921	NEW	NEW	NEW	
Mazda	2	11-14	71	7020K	648487	VS70	707594	7001HP	562515
Mazda	3	04	71	1130K	502902	NO	NO	7001HP	562515
Mazda	3	05-10	71	1050K	502904	NO	NO	7001HP	562515
Mazda	3	10-13	71	7020K	648487	VS70	707594	7001HP	562515
Mazda	5	06-10	71	1050K	502904	NO	NO	7001HP	562515
Mazda	5	10-15	71	7020K	648487	VS70	707594	7001HP	562515
Mazda	6	08-10	71	1050K	502904	NO	NO	7001HP	562515
Mazda	6	10-13	71	7020K	648487	VS70	707594	7001HP	562515
Mazda	B-Series	07-09	---	band	1194 band	NO	NO	7001HPR	562517
Mazda	CX-7	07-10	71	1050K	502904	NO	NO	7001HP	562515
Mazda	CX-7	10-12	71	7020K	648487	VS70	707594	7001HP	562515
Mazda	CX-9	07-10	71	1050K	502904	NO	NO	7001HP	562515
Mazda	CX-9	10-15	71	7020K	648487	VS70	707594	7001HP	562515
Mazda	MX-5 Miata	06-10	71	1050K	502904	NO	NO	7001HP	562515
Mazda	MX-5 Miata	10-15	71	7020K	648487	VS70	707594	7001HP	562515
Mazda	RX-8	04	71	1130K	502902	NO	NO	7001HP	562515
Mazda	RX-8	05-10	71	1050K	502904	NO	NO	7001HP	562515
Mazda	RX-8	10-11	71	7020K	648487	VS70	707594	7001HP	562515
Mazda	Tribute	05-08	---	band	1194 band	NO	NO	7001HPR	562517
Mazda	Tribute	09-11	---	VS950	502975	VS950	502975	7001HPR	562517
McLaren	MP4-12c	12-13	35	1096	300415	1096	300415	9011	574593
M-Benz	AMG GT S	16	53	1100K	502921	NEW		28214	467085
M-Benz	B-Class	14-15	53	1100K	502921	NEW		28214	467085
M-Benz	C-Class	08-14	53	2030K	502970	9066K	648491	28214	467085
M-Benz	C-Class	15	53	1100K	502921	NEW		28214	467085
M-Benz	CL-Class	01-06	35	1090K	502980	1094	502992	9004	489773
M-Benz	CL-Class	07-09	53	1040K	502977	1040K	502977	7003 or 1054	882760 (RS) or 503010
M-Benz	CL-Class	10-14	53	2030K	502970	9066K	648491	28214	467085
M-Benz	CLA-Class	14-15	53	1100K	502921	NEW		28214	467085
M-Benz	CLK-Class	08-09	53	2030K	502970	9066K	648491	28214	467085
M-Benz	CLS-Class	06-11	53	1040K	502977	1040K	502977	7003 or 1054	882760 (RS) or 503010
M-Benz	CLS-Class	12-14	53	2030K	502970	9066K	648491	28214	467085
M-Benz	CLS-Class	15	53	1100K	502921	NEW		28214	467085
M-Benz	E-Class	03-06	35	1090K	502980	1094	502992	9004	489773
M-Benz	E-Class	07-09	53	1040K	502977	1040K	502977	7003 or 1054	882760 (RS) or 503010
M-Benz	E-Class	10-14	53	2030K	502970	9066K	648491	28214	467085
M-Benz	E-Class	15	53	1100K	502921	NEW		28214	467085
M-Benz	G-Class	07-15	53	2030K	502970	9066K	648491	28214	467085
M-Benz	GL-Class	07-09	53	1040K	502977	1040K	502977	1049	574586
M-Benz	GL-Class	10-14	53	2030K	502970	9066K	648491	28214	467085
M-Benz	GL-Class	15	53	1100K	502921	NEW		28214	467085
M-Benz	GLA-Class	15	53	1100K	502921	NEW		28214	467085
M-Benz	GLK-Class	10-14	53	2030K	502970	9066K	648491	28214	467085
M-Benz	GLK-Class	15	53	1100K	502921	NEW		28214	467085
M-Benz	ML-Class	07-09	53	1040K	502977	1040K	502977	1049	574586
M-Benz	ML-Class	10-14	53	2030K	502970	9066K	648491	28214	467085
M-Benz	ML-Class	15	53	1100K	502921	NEW		28214	467085
M-Benz	R-Class	07-09	53	1040K	502977	1040K	502977	1049	574586
M-Benz	R-Class	10-12	35	2030K	502970	9066K	648491	28214	467085
M-Benz	S-Class	01-06	35	1090K	502980	1094	502992	9004	489773
M-Benz	S-Class	07-09	53	1040K	502977	1040K	502977	7003 or 1054	882760 (RS) or 503010
M-Benz	S-Class	10-14	53	2030K	502970	9066K	648491	28214	467085
M-Benz	S-Class	15	53	1100K	502921	NEW		28214	467085
M-Benz	SL-Class	03-05	35	1090K	502980	1094	502992	9004	489773
M-Benz	SL-Class	06-12	53	1040K	502977	1040K	502977	7003 or 1054	882760 (RS) or 503010
M-Benz	SL-Class	13-14	53	2030K	502970	9066K	648491	28214	467085
M-Benz	SL-Class	15	53	1100K	502921	NEW		28214	467085
M-Benz	SLK-Class	08-14	53	2030K	502970	9066K	648491	28214	467085
M-Benz	SLK-Class	15	53	1100K	502921	NEW		28214	467085
M-Benz	SLR McLaren (315 MHz)	05-07	35	1090K	502980	1094	502992	9004	489773
M-Benz	SLR McLaren (433 MHz)	05-07	35	1090K	502980	1094	502992	9001	545608
M-Benz	SLR McLaren (315 MHz)	08-09	53	1040K	502977	1040K	502977	7003 or 1054	882760 (RS) or 503010
M-Benz	SLR McLaren (433 MHz)	08-09	53	1040K	502977	1040K	502977	1049	574586
M-Benz	SLS AMG	11-15	53	2030K	502970	9066K	648491	28214	467085
M-Benz	Sprinter	07-13	54	1098K	503006	1098K	503006	1042	574595
M-Benz	Sprinter	14-15	53	2030K	502970	9066K	648491	28214	467085
Mercury	Grand Marquis	08-10	---	band	1194 band	NO	NO	7001HPR	562517
Mercury	Mariner	05-08	---	band	1194 band	NO	NO	7001HPR	562517
Mercury	Mariner	09-11	---	VS950	502975	VS950	502975	7001HPR	562517

DILL TPMS APPLICATIONS CHART ©

Make	Model	Model Year Range	OE Torque In-Lbs	Dill Kit	Costco Kit	Valve Stem Replacement	Costco Valve	Dill/Costco	Costco
Mercury	Milan	08-09	---	band	1194 band	NO	NO	7001HPR	562517
Mercury	Milan	10-11	---	VS950	502975	VS950	502975	7001HPR	562517
Mercury	Monterey	06-07	---	band	1194 band	NO	NO	7001HPR	562517
Mercury	Mountaineer	03-05	44	1060K	502905	NO	NO	7004	562516
Mercury	Mountaineer	06-10	---	band	1194 band	NO	NO	7001HPR	562517
Mercury	Sable	08-09	---	band	1194 band	NO	NO	7001HPR	562517
** Note: Redi-Sensor relearn must be performed with a scan tool, not a magnet.									
Mini	Hatchback/Cabrio	07-09	35	1090K	502980	1091-1095	502980, 502981, 502992, or 502997	1027	562514
Mini	Hatchback/Cabrio	10-14	40	1096	300415	1096	300415	9012	574594
Mini	Cabrio (Post March 2014)	14-15	40	1096	300415	1096	300415	9017	728984
Mini	Clubman	08-09	35	1090K	502980	1091-1095	502980, 502981, 502992, or 502997	1027	562514
Mini	Clubman	10-14	40	1096	300415	1096	300415	9012	574594
Mini	Clubman (Post July 2014)	14	71	7020K	648487	VS70	707594	5256	938131
Mini	Countryman	11-14	40	1096	300415	1096	300415	9012	574594
Mini	Countryman (Post March 2014)	14-15	40	1096	300415	1096	300415	9017	728984
Mini	Coupe	12-14	40	1096	300415	1096	300415	9012	574594
Mini	Coupe (Post March 2014)	14-15	40	1096	300415	1096	300415	9017	728984
Mini	Hatchback	14-15	71	7020K	648487	VS70	707594	5256	938131
Mini	Paceman	13-14	40	1096	300415	1096	300415	9012	574594
Mini	Paceman (Post March 2014)	14-15	40	1096	300415	1096	300415	9017	728984
Mini	Roadster	12-14	40	1096	300415	1096	300415	9012	574594
Mini	Roadster (Post March 2014)	14-15	40	1096	300415	1096	300415	9017	728984
Mitsubishi	Eclipse (w/ Alloy wheels)	08-12	45-53	1080K	502913	NO	NO	7001HP	562515
Mitsubishi	Eclipse (w/ Steel wheels)	08-09	45-53	1130K	502902	NO	NO	7001HP	562515
Mitsubishi	Endeavor	04-06	45-53	1080K	502913	NO	NO	7004	562516
Mitsubishi	Endeavor (w/ Steel wheels)	07-08	45-53	1130K	502902	NO	NO	7001HP	562515
Mitsubishi	Endeavor (w/ Alloy wheels)	07-11	45-53	1080K	502913	NO	NO	7001HP	562515
Mitsubishi	Galant	06	45-53	1080K	502913	NO	NO	7004	562516
Mitsubishi	Galant (w/ Alloy wheels)	07-12	45-53	1080K	502913	NO	NO	7001HP	562515
Mitsubishi	Galant (w/ Steel wheels)	07-09	45-53	1130K	502902	NO	NO	7001HP	562515
Mitsubishi	i-MiEV**	12-14	71	7020K	648487	VS70	707594	7001HP	562515
Mitsubishi	Lancer**	08-10	71	1050K	502904	NO	NO	7001HP	562515
Mitsubishi	Lancer**	10-15	71	7020K	648487	VS70	707594	7001HP	562515
Mitsubishi	Mirage**	14	---	VS90	863920	VS90	863920	7001HPR	562517
Mitsubishi	Mirage (Post Sept. 2013)**	14	71	7020K	648487	VS70	707594	7001HP	562515
Mitsubishi	Montero (w/ Alloy wheels)	03-06	45-53	1080K	502913	NO	NO	7001HP	562515
Mitsubishi	Montero (w/ Steel wheels)	03-06	45-53	1130K	502902	NO	NO	7001HP	562515
Mitsubishi	Outlander**	07-10	71	1050K	502904	NO	NO	7001HP	562515
Mitsubishi	Outlander and Sport**	10-15	71	7020K	648487	VS70	707594	7001HP	562515
Mitsubishi	Outlander Sport**	13	---	VS90	863920	VS90	863920	7001HPR	562517
Mitsubishi	Raider	08-09	53	9066K	502970	9066K	648491	7001HP	562515
Mitsubishi	RVR**	11-15	71	7020K	648487	VS70	707594	7001HP	562515
Mitsubishi	RVR**	13	---	VS90	863920	VS90	863920	7001HPR	562517
** Note: Vehicle relearn will require an additional Mitsubishi-specific activation tool made by Bartec.									
Nissan	350Z	03-06	45-60	1080K	502913	NO	NO	7001HP	562515
Nissan	350Z	07-09	50-70	2030K	502970	NO	NO	7001HP	562515
Nissan	370Z	09-10	35	1100K	502921	NO	NO	7001HP	562515
Nissan	370Z	10-15	35	1100K	502921	NO	NO	7003 or 1216	882760 (RS) or 643321
Nissan	Altima	07-11	50-70	2030K	502970	NO	NO	7001HP	562515
Nissan	Altima	12	71	7020K	648487	VS70	707594	7001HP	562515
Nissan	Altima Coupe	13	71	7020K	648487	VS70	707594	7001HP	562515
Nissan	Altima Sedan	13-15	71	7020K	648487	VS70	707594	5556	863892
Nissan	Armada (w/ Alloy wheels)	04-07	49	1080K	502913	NO	NO	7001HP	562515
Nissan	Armada (w/ Steel wheels)	05-06	49	1130K	502902	NO	NO	7001HP	562515
Nissan	Armada	09-15	50-70	2030K	502970	NO	NO	7001HP	562515
Nissan	Cube (<11/11)	09-12	50-70	2030K	502970	NO	NO	7001HP	562515
Nissan	Cube 1.8 & 1.8 S CVT (11/11-3/12)	12	50-70	2030K	502970	NO	NO	7001HP	562515
Nissan	Cube-1.8 SL (10/10-11/11)	11-12	71	7020K	648487	VS70	707594	5557	863894
Nissan	Cube 1.8 & 1.8S (3/12-9/13)	12-13	35	1100K	502921	NO	NO	7001HP	562515
Nissan	Cube 1.8 S CVT (>11/11)	12-14	35	1100K	502921	NO	NO	7003 or 1216	882760 (RS) or 643321
Nissan	Frontier	03-04	45-60	1080K	502913	NO	NO	7001HP	562515
Nissan	Frontier (w/ Alloy wheels)	05-08	49	1080K	502913	NO	NO	7001HP	562515
Nissan	Frontier (w/ Steel wheels)	05-08	49	1130K	502902	NO	NO	7001HP	562515
Nissan	Frontier (5/08 - 10/13)	09-14	50-70	2030K	502970	NO	NO	7001HP	562515
Nissan	Frontier (1/12 - 10/13)	12-15	71	7020K	648487	VS70	707594	7001HP	562515
Nissan	GT-R	09-15	50-70	2030K	502970	NO	NO	7001HP	562515
Nissan	Juke Base (w/out I-Key <3/12)	11	50-70	2030K	502970	NO	NO	7001HP	562515
Nissan	Juke SV & SL (w/ I-Key-- 7/10 - 7/11)	11	35	1100K	502921	NO	NO	7003 or 1216	882760 (RS) or 643321
Nissan	Juke (w/ I-Key-- 7/11 - 9/11)	11	71	7020K	648487	VS70	707594	5557	863894
Nissan	Juke Base (w/out I-Key--Post 3/12)	12-15	35	1100K	502921	NO	NO	7001HP	562515
Nissan	Juke (w/ I-Key--Post 2/12)	12-15	35	1100K	502921	NO	NO	7003 or 1216	882760 (RS) or 643321
Nissan	Leaf	11	35	1100K	502921	NO	NO	7003 or 1216	882760 (RS) or 643321
Nissan	Leaf	12-13	35	1100K	502921	NO	NO	1216	643321
Nissan	Leaf (> 12/12)	13-15	71	7020K	648487	VS70	707594	5557	863894
Nissan	Maxima	07	49	1080K	502913	NO	NO	7001HP	562515
Nissan	Maxima	07-12	50-70	2030K	502970	NO	NO	7001HP	562515
Nissan	Maxima	12-15	71	7020K	648487	VS70	707594	7001HP	562515
Nissan	Maxima	16	71	7020K	648487	VS70	707594	5556	863892
Nissan	Murano	03-06	45-60	1080K	502913	NO	NO	7001HP	562515
Nissan	Murano	07-12	50-70	2030K	502970	NO	NO	7001HP	562515
Nissan	Murano (Post Nov. 2011)	12-14	35	1100K	502921	NO	NO	7001HP	562515
Nissan	Murano	15	71	7020K	648487	VS70	707594	5556	863892

DILL TPMS APPLICATIONS CHART ©

Make	Model	Model Year Range	OE Torque In-Lbs	Dill Kit	Costco Kit	Valve Stem Replacement	Costco Valve	Dill/Costco	Costco
Nissan	NV200	13-15	50-70	2030K	502970	NO	NO	7001HP	562515
Nissan	NV 1500/2500HD/3500HD	12-15	50-70	2030K	502970	NO	NO	NEW	
Nissan	Pathfinder	03-04	45-60	1080K	502913	NO	NO	7001HP	562515
Nissan	Pathfinder (w/ Steel wheels)	04	49	1130K	502902	NO	NO	7001HP	562515
Nissan	Pathfinder	05-06	49	1080K	502913	NO	NO	7001HP	562515
Nissan	Pathfinder	07-12	50-70	2030K	502970	NO	NO	7001HP	562515
Nissan	Pathfinder	13-15	71	7020K	648487	VS70	707594	5556	863892
Nissan	Quest (w/ Steel wheels)	04-07	49	1130K	502902	NO	NO	7001HP	562515
Nissan	Quest (w/ Alloy wheels)	04-06	49	1080K	502913	NO	NO	7001HP	562515
Nissan	Quest	07-09	50-70	2030K	502970	NO	NO	7001HP	562515
Nissan	Quest	11-15	35	1100K	502921	NO	NO	1216	643321
Nissan	Rogue	08-11	50-70	2030K	502970	NO	NO	7001HP	562515
Nissan	Rogue	12-13	35	1100K	502921	NO	NO	7001HP	562515
Nissan	Rogue Select	14-15	50-70	2030K	502970	NO	NO	7001HP	562515
Nissan	Rogue (433 MHz)	14-15	71	7020K	648487	VS70	707594	5559	973110
Nissan	Sentra (w/ Alloy wheels)	07-08	49	1080K	502913	NO	NO	7001HP	562515
Nissan	Sentra	07-12	50-70	2030K	502970	NO	NO	7001HP	562515
Nissan	Sentra (> 1/12)	12	35	1100K	502921	NO	NO	7001HP	562515
Nissan	Sentra (> 9/12) w/out I-KEY	13-15	71	7020K	648487	VS70	707594	7001HP	562515
Nissan	Sentra (> 12/12) w/ I-KEY	13-15	71	7020K	648487	VS70	707594	5557	863894
Nissan	Titan (w/ Alloy wheels)	04-07	49	1080K	502913	NO	NO	7001HP	562515
Nissan	Titan (w/ Steel wheels)	04-07	49	1130K	502902	NO	NO	7001HP	562515
Nissan	Titan (Post April 2007)	07-14	50-70	2030K	502970	NO	NO	7001HP	562515
Nissan	Titan	15	71	7020K	648487	VS70	707594	7001HP	562515
Nissan	Versa	07-11	50-70	2030K	502970	NO	NO	7001HP	562515
Nissan	Versa Sedan	12	71	7020K	648487	VS70	707594	7001HP	562515
Nissan	Versa Sedan S and SV	13-15	71	7020K	648487	VS70	707594	7001HP	562515
Nissan	Versa Sedan SL	13-15	71	7020K	648487	VS70	707594	5557	863894
Nissan	Versa Hatchback (Post Jan. 2012)	12-13	35	1100K	502921	NO	NO	7001HP	562515
Nissan	Versa Note S and SV	14-15	71	7020K	648487	VS70	707594	7001HP	562515
Nissan	Versa Note SL	14-15	71	7020K	648487	VS70	707594	5557	863894
Nissan	Xterra	03-04	45-60	1080K	502913	NO	NO	7001HP	562515
Nissan	Xterra	05-07	49	1080K	502913	NO	NO	7001HP	562515
Nissan	Xterra (w/ Steel wheels)	05-07	49	1130K	502902	NO	NO	7001HP	562515
Nissan	Xterra (<10/13)	08-13	50-70	2030K	502970	NO	NO	7001HP	562515
Nissan	Xterra	13-14	71	7020K	648487	VS70	707594	7001HP	562515
Plymouth	Prowler	97-01	35	1080K	502913	NO	NO	8004	Dealer relearn only
Pontiac	G3	09	---	VS950	502975	VS950	502975	9153	Dealer relearn only
Pontiac	G5	08	71	1050K	502904	NO	NO	7001HP	562515
Pontiac	G5	09-10	---	VS950	502975	VS950	502975	7001HPR	562517
Pontiac	G6 (Pre-10/15/07)	08	71	1050K	502904	NO	NO	7001HP	562515
Pontiac	G6 (Post-10/15/07)	08-10	---	VS950	502975	VS950	502975	7001HPR	562517
Pontiac	G8	08-09	---	VS950	502975	VS950	502975	7001HPR	562517
Pontiac	Grand Prix	07-08	71	1050K	502904	NO	NO	7001HP	562515
Pontiac	Grand Prix	08	---	VS950	502975	VS950	502975	7001HPR	562517
Pontiac	Montana	08-09	62	1070K	502911	NO	NO	7001HP	562515
Pontiac	Solstice	08-09	71	1050K	502904	NO	NO	7001HP	562515
Pontiac	Torrent	07-09	71	1050K	502904	NO	NO	7001HP	562515
Pontiac	Vibe	08-10	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Pontiac	Wave	08-10	---	VS950	502975	VS950	502975	9153	Dealer relearn only
** Note: The 1050K is to be used on the Siemens sensors and the 1070K is to be used on the Schrader sensors.									
Porsche	911	06-08	31-40	1090K	502980	1092	502980	9001	545608
Porsche	911 (non-Turbo)	09-11	31-40	1090K	502980	1092	502980	9011	574587 or 574593
Porsche	911 Turbo	09	31-40	1090K	502980	1092	502980	9001	545608
Porsche	911 Turbo	10-11	40	1096	300415	1096	300415	9011	574593
Porsche	911	12-15	40	1096	300415	1096	300415	9011	574593
Porsche	Boxster	06-08	31-40	1090K	502980	1092	502980	9001	545608
Porsche	Boxster	09-11	31-40	1090K	502980	1092	502980	9011	574587 or 574593
Porsche	Boxster	12-15	40	1096	300415	1096	300415	9011	574593
Porsche	Carrera GT	04-06	31-40	1090K	502980	1092	502980	9001	545608
Porsche	Cayenne	03-06	31-40	1090K	502980	1092	502980	9005	574094
Porsche	Cayenne	08-10	31-40	1090K	502980	1092	502980	9011	571724 or 574593
Porsche	Cayenne	11-14	40	1096	300415	1096	300415	9011	574593
Porsche	Cayenne	15-16	40	1096	300415	1096	300415	9018	
Porsche	Cayman	06-08	31-40	1090K	502980	1092	502980	9001	545608
Porsche	Cayman	09-10	31-40	1090K	502980	1092	502980	9011	574587 or 574593
Porsche	Cayman	11-15	40	1096	300415	1096	300415	9011	574593
Porsche	Macan	15	40	1096	300415	1096	300415	9018	
Porsche	Panamera	10-11	31-40	1090K	502980	1092	502980	9011	574587 or 574593
Porsche	Panamera	12-13	40	1096	300415	1096	300415	9011	574593
Porsche	Panamera	14-15	40	1096	300415	1096	300415	9018	
RAM	1500/2500/3500 pickup	11-13	---	VS950	502975	VS950	502975	9398	574016
RAM	4-wheel Pickup	14-16	---	VS65	938120	VS65	938120	6815	863898
RAM	6-wheel Pickup (3500) Outer Steel Wheel Sensor	14-16	---	VS65	938120	VS65	938120	6815	863898
RAM	6-wheel Pickup (3500) Outer Alloy Wheel Sensor	14-16	80-125	VS35	938121	VS35	938121	6829	752311
RAM	6-wheel Pickup (3500) Inner Rear Wheel Sensor	14-16	---	VS65	938120	VS65	938120	6825	752304
RAM	Cargo Van (C/V)	12-15	---	VS950	502975	VS950	502975	9398	574016
RAM	Dakota	11	---	VS950	502975	VS950	502975	7001HPR	562517
RAM	Promaster	14-15	71	1100K	502921	NEW		28214	467085
RAM	Promaster City	15	71	1100K	502921	NEW		28214	467085
Rolls Royce	Drophead Coupe	09-14	31-40	1090K	502980	1092 or 1094	502980 or 502992	1027	562514
Rolls Royce	Ghost	10-11	31-40	1090K	502980	1092 or 1094	502980 or 502992	1027	562514
Rolls Royce	Ghost (Post Sept. 2010)	11-14	40	1096	300415	1096	300415	9012	574594
Rolls Royce	Phantom	07-11	31-40	1090K	502980	1092 or 1094	502980 or 502992	1027	562514
Rolls Royce	Phantom	12-14	40	1096	300415	1096	300415	9012	574594

DILL TPMS APPLICATIONS CHART ©

Make	Model	Model Year Range	OE Torque In-Lbs	Dill Kit	Costco Kit	Valve Stem Replacement	Costco Valve	Dill/Costco	Costco
Rolls Royce	Wraith	14	40	1096	300415	1096	300415	9012	574594
Saab	9-3	03-07	62	2010K	502930	NO	NO	28078	296755
Saab	9-3	08-11	44	2010K	502930	NO	NO	9159	1006949
Saab	9-4x	11	---	VS950	502975	VS950	502975	7001HPR	562517
Saab	9-5	08-09	44	2010K	502930	NO	NO	9159	Dealer relearn only
Saab	9-5	10-11	---	VS950	502975	VS950	502975	7001HPR	562517
Saab	9-7X	07-09	62	1070K	502911	NO	NO	7001HP	562515
Saturn	Astra	08-09	62	2010K	502930	NO	NO	28078	296755
Saturn	Aura (<10/14/07)	07-08	71	1050K	502904	NO	NO	7001HP	562515
Saturn	Aura (>10/14/07)	08-09	---	VS950	502975	VS950	502975	7001HPR	562517
Saturn	Outlook	07-08	71	1050K	502904	NO	NO	7001HP	562515
Saturn	Outlook	09-10	---	VS950	502975	VS950	502975	7001HPR	562517
Saturn	Sky	08-09	71	1050K	502904	NO	NO	7001HP	562515
Saturn	Vue	08-10	---	VS950	502975	VS950	502975	7001HPR	562517
** Note: The 1050K is to be used on the Siemens sensors and the 1070K is to be used on the Schrader sensors.									
Scion	FR-S	13-15	35	1100K	502921	NO	NO	7003 or 1218	882760 (RS) or 643351
Scion	iQ	12-15	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Scion	tC	07-15	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Scion	xB	08-15	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Scion	xD	08-14	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Smart	Fortwo	08-15	53	2030K	502970	9066K	648491	28214	467085
Subaru	B9 Tribeca	06-07	66	1080K	502913	NO	NO	7003	882760
Subaru	BRZ	13-16	35	1100K	502921	NO	NO	7003 or 1218	882760 (RS) or 643351
Subaru	Forester	08-16	---	VS950	502975	VS950	502975	7003	882760
Subaru	Impreza	08-16	---	VS950	502975	VS950	502975	7003	882760
Subaru	Legacy	07	66	1080K	502913	NO	NO	7003	882760
Subaru	Legacy	08-16	---	VS950	502975	VS950	502975	7003	882760
Subaru	Outback	05-07	66	1080K	502913	NO	NO	7003	882760
Subaru	Outback	08-16	---	VS950	502975	VS950	502975	7003	882760
Subaru	Tribeca	08-14	---	VS950	502975	VS950	502975	7003	882760
Subaru	WRX & STI	15-16	---	VS950	502975	VS950	502975	7003	882760
Subaru	XV Crosstrek	13-16	---	VS950	502975	VS950	502975	7003	882760
Suzuki	Equator	09-12	68	2030K	502970	NO	NO	7001HP	562515
Suzuki	Forenza	07-08	---	VS950	502975	VS950	502975	7001HPR	562517
Suzuki	Grand Vitara**	07-13	80	2010K	502930	NO	NO	20087	296736
Suzuki	Kizashi	10-13	71	7020K	648487	VS70	707594	7001HP	562515
Suzuki	Reno	07-08	---	VS950	502975	VS950	502975	7001HPR	562517
Suzuki	SX4**	07-13	80	2010K	502930	NO	NO	20087	296736
Suzuki	Verona	05-06	80	2010K	502930	NO	NO	20082	296735
Suzuki	XL-7	05-06	80	2010K	502930	NO	NO	20087	296736
Suzuki	XL-7	07-09	71	1050K	502904	NO	NO	7001HP	562515
** Note: Vehicle relearn will require an additional Mitsubishi/Suzuki-specific activation tool made by Bartec.									
Tesla	Roadster (VIN 001-500)	08-10	40	1096	300415	1096	300415	9011	574593
Tesla	ALL (BaoLong)	10-14	40-50	TP416L		TP416L		2112	855918
Tesla	Model S (Silver Continental)	14	71	7020K	648487	VS70	707594	2168	1022452
Tesla	Model S (Black Continental)	14	71	7020K	648487	VS70B		2168	1022452
Toyota	4 Runner	04-15	35	1100K	502923	NO	NO	7002 or 7002A	707597 or 1022490
Toyota	Avalon	07-12	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Toyota	Avalon	13-16	35	1100K	502921	NO	NO	7003 or 1218	882760 (RS) or 643351
Toyota	Camry	07-11	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Toyota	Camry	12-14	35	1100K	502921	NO	NO	7003 or 1218	882760 (RS) or 643351
Toyota	Camry w/ centered speedometer	15-16	35	1100K	502921	NO	NO	7003 or 1218	882760 (RS) or 643351
Toyota	Camry w/ centered colored screen	15-16	35	1100K	502921	NO	NO	1230	
Toyota	Corolla	07-13	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Toyota	Corolla	14-16	35	1100K	502921	NO	NO	7003 or 1218	882760 (RS) or 643351
Toyota	FJ Cruiser	08-14	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Toyota	Highlander	07-13	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Toyota	Highlander (w/ Smart Key)	14-15	35	1100K	502921	NO	NO	7003 or 1218	882760 (RS) or 643351
Toyota	Highlander (w/out Smart Key)	14-15	35	1100K	502921	NO	NO	1225	939171
Toyota	Land Cruiser	06-14	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Toyota	Land Cruiser	15	35	1100K	502921	NO	NO	7003 or 1218	882760 (RS) or 643351
Toyota	Matrix	07-13	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Toyota	Prius	06-15	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Toyota	Prius V	12-15	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Toyota	Prius C	12-15	35	1100K	502921	NO	NO	7003 or 1218	882760 (RS) or 643351
Toyota	RAV 4	06-12	35	1100K	502921	NO	NO	7002** or 7002A**	707597** or 1022490**
Toyota	RAV 4 Electric Vehicle (EV)	13-14	35	1100K	502921	NO	NO	7002** or 7002A**	707597** or 1022490**
Toyota	RAV4 non-EV (w/ Smart Key)	13-15	35	1100K	502921	NO	NO	7003 or 1218	882760 (RS) or 643351
Toyota	RAV4 non-EV (Made in Japan w/out Smart Key)	13-15	35	1100K	502921	NO	NO	7003 or 1218	882760 (RS) or 643351
Toyota	RAV4 non-EV (Made in Canada w/out Smart Key)	13-15	35	1100K	502921	NO	NO	1225	939171
Toyota	Sequoia (w/ Alloy wheels)	05-07	35	1100K	502923	NO	NO	7002 or 7002A	707597 or 1022490
Toyota	Sequoia (w/ Steel wheels)	05-07	35	1100K	502923	NO	NO	7002 or 7002A	707597 or 1022490
Toyota	Sequoia (20 Degrees)	08-15	35	1100K	502923	NO	NO	7002 or 7002A	707597 or 1022490
Toyota	Sequoia (40 Degrees)	08	35	1100K	502923	NO	NO	7002 or 7002A	707597 or 1022490
Toyota	Sienna	07-15	35	1100K	502923	NO	NO	7002 or 7002A	707597 or 1022490
Toyota	Solara	07-08	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Toyota	Tacoma (w/ Alloy wheels)	05-06	35	1100K	502923	NO	NO	7002 or 7002A	707597 or 1022490
Toyota	Tacoma (w/ Steel wheels)	05-15	35	1100K	502923	NO	NO	7002 or 7002A	707597 or 1022490
Toyota	Tacoma (w/ Steel wheels)	16	35	1100K	502921	NO	NO	NEW	
Toyota	Tacoma (w/ Alloy wheels)	07-15	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Toyota	Tacoma (w/ Alloy wheels)	16	35	1100K	502921	NO	NO	1230	
Toyota	Tundra (w/ Alloy wheels)	05-06	35	1100K	502923	NO	NO	7002 or 7002A	707597 or 1022490
Toyota	Tundra (w/ Steel wheels)	05-06	35	1100K	502923	NO	NO	7002 or 7002A	707597 or 1022490
Toyota	Tundra (20 Degrees)	07-15	35	1100K	502923	NO	NO	7002 or 7002A	707597 or 1022490

DILL TPMS APPLICATIONS CHART ©

Make	Model	Model Year Range	OE Torque In-Lbs	Dill Kit	Costco Kit	Valve Stem Replacement	Costco Valve	Dill/Costco	Costco
Toyota	Tundra (40 Degrees)	07-11	35	1110K	502923	NO	NO	7002 or 7002A	707597 or 1022490
Toyota	Venza	09-15	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Toyota	Yaris	08-11	35	1100K	502921	NO	NO	7002 or 7002A	707597 or 1022490
Toyota	Yaris	12-15	35	1100K	502921	NO	NO	7003 or 1218	882760 (RS) or 643351
** Note: 406K is needed if the valve hole's counterbore diameter is small than a US dime coin (0.70in).									
Volkswagen	Beetle	08-10	71	1030K	502902	NO	NO	7003 or 1053	882760 (RS) or 506565
Volkswagen	CC	09-11	71	1030K	502902	NO	NO	7003 or 1053	882760 (RS) or 506565
Volkswagen	CC	12-15	40	1096	300415	1096	300415	9013	728983
Volkswagen	EOS	07-15	71	1030K	502902	NO	NO	7003 or 1053	882760 (RS) or 506565
Volkswagen	GLI	08-09	71	1030K	502902	NO	NO	7003 or 1053	882760 (RS) or 506565
Volkswagen	Golf	10-11	71	1030K	502902	NO	NO	7003 or 1053	882760 (RS) or 506565
Volkswagen	GTI	06-11	71	1030K	502902	NO	NO	7003 or 1053	882760 (RS) or 506565
Volkswagen	GTI w/ OE 18in wheels	06-07	71	1031K	574596	NO	NO	7003 or 1041	882760 (RS) or 574265
Volkswagen	Jetta	06-11	71	1030K	502902	NO	NO	7003 or 1053	882760 (RS) or 506565
Volkswagen	Passat	06-10	71	1030K	502902	NO	NO	7003 or 1053	882760 (RS) or 506565
Volkswagen	Passat w/ OE 18in wheels	06-08	71	1031K	574596	NO	NO	7003 or 1041	882760 (RS) or 574265
Volkswagen	Phaeton	04-06	35	1090K	502980	1092	502980	9001	545608
Volkswagen	R32	08	71	1030K	502902	NO	NO	7003 or 1053	882760 (RS) or 506565
Volkswagen	Rabbit	07-09	71	1030K	502902	NO	NO	7003 or 1053	882760 (RS) or 506565
Volkswagen	Routan	09-10	71	1050K	502904	NO	NO	7004	562516
Volkswagen	Routan	11-12	---	VS950	502975	VS950	502975	9398	574016
Volkswagen	Tiguan	09-11	71	1030K	502902	NO	NO	7003 or 1053	882760 (RS) or 506565
Volkswagen	Tiguan	14	40	1096	300415	1096	300415	9013	728983
Volkswagen	Touareg	04-07	35	1090K	502980	1092	502980	9005	574094
Volkswagen	Touareg	08-10	35	1090K	502980	1092	502980	9011	571724 or 574593
Volkswagen	Touareg	11-14	40	1096	300415	1096	300415	9011	574593
Volvo	C30	08-10	71	1050K	502904	NO	NO	7004	562516
Volvo	C30	11-13	71	7020K	648487	VS70	707594	7004	562516
Volvo	C70	08-10	71	1050K	502904	NO	NO	7004	562516
Volvo	C70	11-13	71	7020K	648487	VS70	707594	7004	562516
Volvo	S40	08-10	71	1050K	502904	NO	NO	7004	562516
Volvo	S40	11	71	7020K	648487	VS70	707594	7004	562516
Volvo	S60	05-08	44	2010K	502930	NO	NO	7003	882760
Volvo	S60	08-09	---	VS950	502975	VS950	502975	7003	882760
Volvo	S60	11-13	71	7020K	648487	VS70	707594	7004	562516
Volvo	S60	14-15	71	7020K	648487	VS70	707594	5134	1006628
Volvo	S80	05-06	44	2010K	502930	NO	NO	7003	882760
Volvo	S80	07-10	71	1050K	502904	NO	NO	7004	562516
Volvo	S80	10-13	71	7020K	648487	VS70	707594	7004	562516
Volvo	S80	14-15	71	7020K	648487	VS70	707594	5134	1006628
Volvo	V50	08-10	71	1050K	502904	NO	NO	7004	562516
Volvo	V50	11	71	7020K	648487	VS70	707594	7004	562516
Volvo	V60	15	71	7020K	648487	VS70	707594	5134	1006628
Volvo	V70	05-07	44	2010K	502930	NO	NO	7003	882760
Volvo	V70	08-10	71	1050K	502904	NO	NO	7004	562516
Volvo	XC60	10-13	71	7020K	648487	VS70	707594	7004	562516
Volvo	XC60	14-15	71	7020K	648487	VS70	707594	5134	1006628
Volvo	XC70	05-07	44	2010K	502930	NO	NO	7003	882760
Volvo	XC70	08-10	71	1050K	502904	NO	NO	7004	562516
Volvo	XC70	10-13	71	7020K	648487	VS70	707594	7004	562516
Volvo	XC70	14-15	71	7020K	648487	VS70	707594	5134	1006628
Volvo	XC90 (315 MHz)	05-08	44	2010K	502930	NO	NO	7003	882760
Volvo	XC90 (315 MHz)	08-14	---	VS950	502975	VS950	502975	7003	882760
Volvo	XC90 (433 MHz)	08	71	1050K	502904	NO	NO	7004	562516
VPG	MV-1	11-13	---	VS950	502975	VS950	502975	7001HPR	562517
Volvo Group	Volvo Bus	all	---	VS9013 or VS9980		VS9013 or VS9980		9010	
Volvo Group	Prevost Bus	all	---	VS9013 or VS9980		VS9013 or VS9980		9010	
Volvo Group	Nova Bus	all	---	VS9013 or VS9980		VS9013 or VS9980		9010	

DISCLAIMER: The data presented in this document is accurate to the best of our knowledge and is regularly updated with the latest data available in the marketplace. We encourage you to check back for the latest edition of this data, however, we cannot guarantee accuracy of the information provided. Also, please note that several vehicle applications require knowledge of the VIN number as the sensor design could have changed mid-model year. *PLEASE DO NOT POST THIS DOCUMENT ON ANY WEBSITE.*